

MARIS

PARTITION FS - CS Floor slab to ceiling slab

Sound barrier partition

SV = 'In floor void'

CV = 'In ceiling void'

Fire barrier partition
FV = 'In floor void'
CV = 'In ceiling void'

PARTITION P Plywood partition strength

BTRENGTHENING M Mdf partition strengthening


GLAZING DETAILS


Existing silicon glass
Existing glazed module
New single glazed silicon glass
New double glazed silicon glass
New single glazed silicon glass
New single glazed module
New double glazed module

EX1=Existing 1st floor (N1-01)N1 =New 1st floor (X1-01) RX1=Relocated 1st floor

V.P. = Vision panel 01 =Door No. SEC = Security door FD20S = Fire door rated with smoke seal FD20S =20 min FD30S =30 min FD60S =60 mir

R1 = 1st floor room 01 = Room no. W1 = 1st floor window 01 = Window no.







QUALITY CONTROL

CLIENT

Orion Engineering

 19938
 O1
 1st
 GA
 M

 Project No
 Building
 Floor
 Detail
 Rev
 The Signal Building

24/03/2015

 MARIS INTERIORS LLP

 The Harlequin Building
 T
 020 7902 1750

 65 Southwark Street
 E
 marks flimatic-interiors. co.uk

 London SE1 0HR
 W
 marks-interiors. co.uk